



Remove screen by turning counter-clockwise.



Clean intake area using a soft bristled brush or cloth and low foam soap to remove any visible residue. Rinse with sprayhead - Cold water



Clean back of screen Jet with same soft brush or cloth. Rinse with cold water



Replace screen by turning clockwise